ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0620, W0624	3rd Crs, 4th Crs	DEFENCE COLONY
Segment No.	**Total Length (m)**	
14/S-W0620/S064514	60.06	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	28.41	77.506114	13.052835	77.506373	13.052796	W0824	DEAD END
2	31.65	77.507163	13.053078	77.507449	13.053018	W0835	M0001

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENT TO DRAIN AT 5TH AND 1ST B CROSS ROAD AT DEFENCE COLONY	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	DRAIN WORK	014-14-000031
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/715/14-15		
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		1494850.00
Phone No.	**E-Mail ID**	
9743188999		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಕೊಗಿಲಚಂಟಿ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Field Inspection Details

Number of Trees

0

Any Other Information

Name

manjunath

Date of Inspection

19/03/2016

Remarks

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	19/03/2016	18/04/2016	COMPLETED
EE	SRINIVAS	19/03/2016	18/04/2016	COMPLETED
AEE	RANGASWAMY	19/03/2016	18/04/2016	COMPLETED
AE	MANJUNATH	19/03/2016	18/04/2016	COMPLETED
AE	MANJUNATH	19/03/2016	18/04/2016	COMPLETED